



CRAFTING IDEA

GB

Wreath out of the kneading-cement



Used items:

33 068 00	Styrofoam-ring, flat	1 piece
34 212 000	Creative kneading-cement	1 bag / 3 kg
33 384 000	Glue for foil	
81 283 22	Decor-Metallic-foil, silver	

Additionally you need:

Container for kneading of the cement (e.g. bowl with lid), disposable gloves, brush, small container with water, stable support e.g. the lid of a plastic bucket, PET spray bottle (item 38 798 000), turntable ø 28 cm (item 89 259 00)

Instructions:

1 Thus the kneading-cement is not too dry, we recommend you to work it out in 3 sections. Always wear plastic gloves while working!

2 Mix 1/3 of the cement (1 kg) with water in the ratio 9:1 (9 parts of cement : 1 part of water). This corresponds to about 110 ml. Stir the water slowly, gradually add it while constantly kneading. Knead the crumbly mixture with damp disposable gloves (if necessary, moisten several times) until the desired consistency is achieved.

Hint You can mix also, quickly and easily, the kneading-cement in a sealable container. Here also add the water gradually by stirring it constantly, then close the container and shake it well. That way there is less dust and the parts intermix perfectly. Knead more afterwards the crumbly mixture with wet disposable gloves (if necessary, moisten several times) until the mixture is malleable.

3 Take some cement between the palms, press it flat and coat about a third of the flat styrofoam-ring until this section is thinly coated with the cement.

4 Mould a hazelnut-sized pellets out of the kneading-cement, tap them flat between the palms, mould them malleably and press them scale-like onto the wreath-section coated with cement (poss. stop up the joints with your thumb).



Hint The cement mixture should be smooth and easily malleable. If the cement is cracky during kneading, just sprinkle it with some water. The connection joints should be always damp, potentially work it out with a lightly moistened brush.

5 Once the coated wreath-section decorated, mix the second and further the last one i.e. the third kneading-cement and start with the next section in the same manner.

6 Let it dry. The entire drying period lasts for several days. After about 21 days the object is weatherproof.

7 Optionally, you can decorate further the wreath with silver highlights. Therefor, spread some glue for foil onto the "leaf points" by using the brush and let it dry clearly (it lasts at least 1 hour). Then decorate it with the mirror-foil according to the package instructions.

Rayher.

KALEIDO 1 Brasov,

KALEIDO 2 Brasov, str. Dr. Liviu Cimpeanu nr.47

Tel : 0726 244 171

www.rayherhobby.ro

sos. Cristianului nr.1-3

Tel : 0726 244 174

Tel : 0726 244 174

www.kaleido.ro

